





Interior documentation / Fire documentation of metal deck underside




Interior documentation / Fire documentation of metal deck underside

[REDACTED]



Killeen Transfer Station Seam documentation / Seam height 3"



Killeen Transfer Station Panel width 22.5"



Interior documentation / Fire documentation of metal deck underside



Fire damage to east Exposure / ABC (ACM) Metal Panels

[REDACTED]





Fire Damage to East Exposure




Fire Damage

[REDACTED]



Fire Damage



Fire Damage to Panel

[REDACTED]





Roof Penetration at Fire location and associated damage




Roof Penetration at Fire location

[REDACTED]




Fire damaged ISO Insulation above Fire




Metal Deck / Insulation and Metal Panel





Metal deck substrate / insulation and metal (ACM) panel



Damaged Insulation 1,564 +20% / 2,500 s.f. of estimated damaged Insulation







Metal Ridge documentation



KILLEEN / TRANSFER STATION / PANELS COMPROMISED

[REDACTED]



Insulation documentation



Insulation documentation

[REDACTED]



Insulation documentation