



REPLACEMENT OF IRRIGATION
CONTROLLER AT STONETREE
GOLF COURSE

RS-24-099

June 4, 2024

Background

2

- The golf course irrigation control panel went down in November of 2023. A replacement panel has been rented at a cost of \$1500 monthly. It's been recently brought to our attention that if the rental panel fails, a replacement rental is not available.



Background

- ❑ Staff has sourced a new panel from Pump Mechanical Technical Services, LLC through Texas Purchasing Buyboard Cooperative at (#672-22), meeting the state competitive bidding requirements in Local Government Code 271.102.
- ❑ The equipment has a lifecycle of 10-15 years.
- ❑ The total cost for equipment, labor, and freight is \$86,169.
- ❑ The rental vendor confirmed we can end our lease as soon as the new equipment has been installed.
- ❑ This purchase will be funded through the Golf Course Enterprise Fund.

Staff Recommendation

- Staff recommends approval of the purchase of a new irrigation control panel for Stonetree Golf Course from Pump Mechanical Technical Services, LLC in the amount of \$86,169 through Texas Purchasing Buyboard Cooperative at (#672-22), meeting the state competitive bidding requirements in Local Government Code 271.102.